




# Geberit Installation



US 8155-01

964.143.00.0





# Geberit Service




# Geberit Service



Water flow is insufficient → clean aerator and filters ①②



# Geberit Service



**Service-Handy**

Art. Nr. 115.830.00.1

Please order the user's manual for the service handy at your Geberit company!