



Geberit Installation





US 8156-01

964.144.00.0

■ GEBERIT




Geberit Service




Geberit Service



Water flow is insufficient → clean aerator and filters ①②



Geberit Service



Service-Handy

Art. Nr. 115.830.00.1

Please order the user's manual for the service handy at your Geberit company!