




# Geberit Installation



US 7949-01

994.993.00.0




# Geberit Service





# Geberit Service



Water flow is insufficient → clean aerator and filters ①②



# Geberit Service



## Service-Handy

Art. Nr. 115.830.00.1

Please order the user's manual for the service handy at your Geberit company!

**■ GEBERIT**