


# Geberit Installation





US 7948-01


994.992.00.0

**■ GEBERIT**





# Geberit Service




# Geberit Service



Water flow is insufficient → clean aerator and filters ①②



# Geberit Service



**Service-Handy**

Art. Nr. 115.830.00.1

Please order the user's manual for the service handy at your Geberit company!